2RF 958/

2111 453	- 1	•
DICT		~
DIST		
MIN A		_
N H S CH D B	_	
CH DB		_
IVAL GJ		_
J G		-
10		-
RA DW		_
RA DW		-
VIBI		
VI B J MAN, L K	_	-
YTJ G E EH SHJM Y W A		
G		
E EH		
SH, J M	Χ	
Y W A		Γ
TER AW		Г
G D		
14	λ	
STIC J.R		
X G E		
X.G.E. ONALD M.M.		<u> </u>
AN RV	X	
ER G L	X	
UTO V M		
JER BL		
JER RI		_
IVAN MT NSON E R		_
NSON E R		
MAN. K.G.		<b>-</b>
E,J	1	<u> </u>
	X	
M L NC	_	_
10	_	<u> </u>
3	<b>.</b>	<u> </u>
nedy, CE	X.	ļ
nison, EA	Δ	├—
nston LD	-	-
th. TA	-	╁╌
		$\vdash$
		-
not, M.K	V	├
110- 6 1	×	<del>i</del>
tius Qui	Ź	1
. I F W. S. W. W.		1
m. Kec.	V	
m. Rec.	$\sim$	-
M Trck o	Ÿ	
S CON ROL	حما	<del>i -</del>
	-	<del>  -</del>

ASSIFICATION

JI \_\_SSI ED | IDENTIAL |

ORIZ D CLASSIFIER SIGNATURE

applicable classifican office exemption

PLY TO REP CC NO

ON IT M STATUS

P N I CLOS D

I PAR IAL LA SAM

PPRAYON SINC

A TYPIST INITIALS

EGEG ROCKY FLATS

EG&G ROCKY FLATS INC ROCKY FLATS PLANT PO BOX 464 GOLDEN COLORADO 80402-0464 (303) 966 7000

August 24 1992

92 RF 9581

Terry A Vaeth Manager DOE RFO

Attn S R Grace

SHUTDOWNS OF THE OPERABLE UNIT NO 2 FIELD TREATABILITY UNIT EML 0569 92

Per your verbal request of August 6 1992 we are submitting information relative to recent shutdowns of the Operable Unit No 2 (OU 2) Field Treatability Unit (FTU) Generator failures caused several shutdown periods totalling approximately 13 hours

A defective bearing in the generator unit caused loose rheostat and field wires. A rental generator has been temporarily installed, the defective bearing removed, and a new bearing was ordered to facilitate repair. FTU operations have successfully continued as normal. A summary of the shutdown periods is as follows.

July 25 1992 System down 6 hours to troubleshoot generator problems and repair

July 26 1992 System down 2 hours to repair rheostat wires

July 27 1992 System down 1 1/2 hours to repair rheostat and field wires

July 28 1992 System down 1/2 hour to repair field wire

July 30 1992 System down 3 hours to install rental generator

If you have any questions or require further information please contact D W Pontius at extension 8616 or E A Dillé at extension 8684 both of Remediation Programs

E M Lee Director

Environmental Management

**DWP** cet

Orig and 1 cc T A Vaeth

CC

F R Lockhart DOE RFO

**ADMIN RECORD** 

A-0U0\_-000395

REVIEWED FOR CLASSIFICATION/UGNI

By Kallana

Date 9/10/92 (2000)